



# MOUNTING KIT 1320020-00 JDEERE A+B

**without QA** FOR ALL MAREDO GT HEADS WITH + WITHOUT GEARBOX. Nov'11

ITEM	Quant.	Part Number + Name	Comment
1	2	3008160 Washer M8 DIN 125A	
2	4	3008400 Thick washer M8 DIN 7349	
3	2	3508000 Nut M8 DIN 934	
4	4	3508004 Self lock nut M8 D985	
5	2	3508008 Self lock nut with washer D6926	
6	1	3514004 Self lock nut M14 D985	
7	1	3514040 High nut M14 3d	
8	2	3608251 Bolt M8 x 25 4017 S	
9	2	3608351 Bolt M8 x 35 4017 S	
10	2	3608400 Bolt M8 x 40 DIN 931	
11	1	3614801 Bolt M14 x 80 DIN 933 4017	
12	2	3915330 D shackle 6 mm for JDeere chain	
13	1	3917519 JDeere chain 7x19 mm 6 shackles d5	
14	1	6003030-01 Washer 14-30-3	
15	2	6005229-00 JDeere angle transport lock bracket	
16	1	6005230-00 JDeere anti-tilt plate on U bracket	
17	1	6010628-08 U frame for Jac and JDeere black	
18	2	6720819-02 Pivot bush U bracket GT	
19	1	7405014-03 Ball head for JDeere	

**For(easy) changing the drive side of the head (Right-> Left/ v.v.), see the manual.**

